

## MDTools® 780 Hotfix 07

**Applicability:** MDTools 780 with SP02

**Issues Resolved:**

1. The Copy Multiple command was missing child cavities if some of the footprints cavities were angled.
2. When converting from Virtual to Feature design mode, the alpha angle of angled Footprint Drill Holes was changing.

Date: Oct 22, 2021